

SOUTH VIEW PHOTO



SOUTH VIEW PHOTO




2 EXISTING AND DEMOLITION MONROE STATION SOUTH ELEVATION SCALE: 1/4" = 1'-0"

DEMOLITION NOTES- SOUTH AND WEST BUILDING ELEVATIONS

- 1. ROOF PROFILE OF ORIGINAL HISTORIC MONROE STATION IS STILL INTACT. ROOF JOISTS, AND SHEATHING HAS BEEN OBSERVED. MAINTAIN ORIGINAL HISTORIC HIP ROOF PROFILE.
- 2. DASHED LINE REPRESENTS ORIGINAL MONROE STATIION BUILDING PROFILE. HISTORIC PLANE OF FIRST FLOOR STILL EVIDENT. HISTORIC SECOND FLOOR WALLS AREAS STILL INTACT. REFER TO EXISTING FLOOR PLANS ON SH. A2.1 FOR ADDITIONAL INFORMATION.
- 3. USE SELECTIVE DEMOLITION TO REMOVE ONE STORY, TWO STORY AND ROOF ADDITIONS FROM THE ORIGINAL BUILDING. REFER TO EXISTING FLOOR PLANS ON SH. A2.1 FOR ADDITIONAL INFORMATION.
- 4. REMOVE NON-HISTORIC ELEMENTS OF EXISTING BUILDING INCLUDING EXISTING FOUNDATIONS, REFER TO EXISTING FLOOR PLANS ON SH. A2.1 FOR ADDITIONAL
- 5. REMOVE EXISTING SHINGLE ROOFING SYSTEM. EXISTING HISTORIC ROOF SHEATHING AND ROOF STRUCTURE TO REMAIN. COORDINATE REMOVAL OF EXISTING ROOFING SYSTEM WITH INSTALLATION OF NEW ROOFING SYSTEM TO ENSURE WATERPROOFING AT ALL TIMES DURING CONSTRUCTION.
- 6. REMOVE AND DISCARD NON-HISTORIC FASCIA FABRIC. CONFER WITH ARCHITECT IN FIELD
- 7. HISTORIC WOOD BRACKETS TO BE CAREFULLY REMOVED AND REHABILITATED. REFER TO ELEVATION SHEET A4.1 FOR ADDITIONAL NOTES.
- 8. REMOVE AND DISCARD NON HISTORIC TRIM.
- 9. REMOVE TOP WOOD BOARD SIDING FOR RECONSTRUCTED TRIM. REFER TO WEST ELEVATION SH. A4.1 FOR NOTES ON RECONSTRUCTED TRIM.
- 10. HISTORIC TRIM TO BE REMOVED FOR REHAB AND RE-INSTALLED IN SAME LOCATION.
- 11. CONFIRM EXISTING HISTORIC WINDOW TRIM IS NOT DETERIORATED BEYOND REPAIR. WHERE DETERIORATED BEYOND REPAIR. RECONSTRUCT TO SAME SIZE AND SHAPE TO MATCH HISTORIC TRIM. WHERE EXISTING HISTORIC TRIM IS SALVAGEABLE, STRIP OFF PAINT AND REHABILITATE. CONFER WITH ARCHITECT ON-SITE.
- 12. CONFIRM EXISTING WINDOW SILL IS NOT DETERIORATED BEYOND REPAIR. WHERE DETERIORATED BEYOND REPAIR, RECONSTRUCT TO SAME SIZE AND SHAPE TO MATCH HISTORIC SILL. WHERE EXISTING HISTORIC SILL IS SALVAGEABLE, STRIP OFF PAINT AND REHABILITATE. CONFER WITH ARCHITECT ON-SITE.
- 13. REMOVE EXISTING VINYL SIDING.
- 14. REMOVE EXISTING PLYWOOD BOARD AND GRILL.
- 15. WEST SIDING NUMBERS WS 4 THRU WS 8 AND WS 34 THRU WS 40 SHALL BE REMOVED AND REHABILITATED. CONFIRM NO DAMAGE EXISTS. ALL OTHER SIDING SHALL BE VERIFIED AT FIELD WITH ARCHITECT TO CONFIRM THEY ARE DAMAGED BEYOND REPAIR/ REHAB BEFORE
- 16. REMOVE EXISTING CONCRETE STEPS.
- 17. REMOVE EXISTING NON-HISTORIC PLYWOOD SOFFIT TO EXPOSE HISTORIC WOOD STRIP SOFFIT. CONFER WITH ARCHITECT TO DETERMINE EXTENT OF SALVAGEABLE MATERIAL.



WEST VIEW PHOTO



EXISTING AND DEMOLITION MONROE STATION WEST ELEVATION SCALE: 1/4" = 1'-0"

(1A) SIDING NOTES ON WEST ELEVATION SCALE: 1/2" = 1'-0"

SEE NOTE 15—

WS 10

WS 7

WS 6

WS 4 WS 3

-NOT HISTORIC -


WS 9 WS 8



WEST VIEW PHOTO



SOUTHWEST VIEW PHOTO



HISTORIC MONROE STATION STABILIZATION

SIXTO ARCHITECT INC.

BICY Contract No. C5120085452

BIG CYPRESS NATIONAL PRESERVE


ARCHITECTURE PLANNING INTERIORS

CONSTRUCTION CONSULTING AA 0003591

1501 Venera Ave. Suite 320-A

Coral Gables, Florida

Tel: (305) 569-2993 Fax: (305) 305-569-9701 www.sixtoarch.com



299 ALHAMBRA CIRCLE CORAL GABLES FLORIDA 33134 PH 305 461-3450 FAX 305 461-3650 inbox@douglaswood.biz www.douglaswood.biz

STRUCTURAL ENGINEERS

ISSUE DATE		PHASE
JUNE 12, 2009		CD
RE	VISIONS	
_		

PROFESSIONAL OF RECORD: RAFAEL SIXTO, A.I.A. REGISTRATION NO:

SHEET TITLE:

EXISTING SOUTH AND WEST DEMOLITION ELEVATIONS